

GISD 2018 Bond MEP - Sprinkler Head Replacement Crenshaw



2018 Bond	Crenshaw	Total
Sprinkler Heads	10,000.00	10,000.00
Total	10,000.00	10,000.00

Island Fire	Crenshaw	Total
Exhaust Fans	19,630.73	19,630.73
Total	19,630.73	19,630.73

Difference	-9,630.73	-9,630.73
-------------------	------------------	------------------

Totals:

Construction Cost:		\$19,630.73
6% MEP Fee:		
Owner Contingency:		\$2,000.00
Total Project Cost:	Constr. + Owner	\$21,630.73
Total Bond:		\$10,000.00
Total Difference:	Bond - Total Project	-\$11,630.73



Island Fire & Safety Equipment Co., Inc

d.b.a. A-1 Fire Equipment Co.
3202 Main St.
LaMarque, TX 77568

Phone # (409) 744-4438 Accounting@A-1Fire.com
Fax # (409) 938-1331 www.A-1Fire.com

Estimate

Date	Estimate #
5/27/2020	32817

Name / Address
Galveston Independent School District P. O. Box 660 Galveston, TX 77553

Ship To
Crenshaw Elementry School 406 Hwy 87 Port Boliver, TX 77650

P.O. No.	Terms	Rep	Project
	Net 30	ML	Crenshaw

Description	Qty	Rate	Total
<p>This Price is to fix heads that are blocked, replace drum drips and change heads to wax coated. Scope of work; - To replace the existing upright sprinkler heads with a wax upright type. - Heads that are considered block coverage will be rotated to the pendent position and replaced with a wax type pendant.</p>			
1/2 200 STD BRS UPR K5.6-WAX GL5661200006	353	19.81802	6,995.76
1/2 200 STD BRS PND K5.6-WAX GL5651200006	141	16.92	2,385.72
Labor Crew 2 Men	56	135.00	7,560.00
1" pipe, 90, drum drips	5	319.00	1,595.00
Lift Rental	1	1,094.25	1,094.25
		0.00	0.00
<p>This Quote is only valid for 30 days. After that time we reserve the right to adjust our quote to reflect material and labor cost increases if necessary. Not responsible for Painting of pipe or insulation.. Not responsible for any modification, cutting, painting and patching of ceiling or any part of building. Not responsible for water damage caused by leaking sprinkler components Not responsible for any other service/repair work not listed. Exclusions of any relocation and/or modification to the fire sprinkler main, branch lines, riser, or upgrading any system to complete the above listed work. Not responsible for any existing pipe, fittings, valves, sprinkler heads or any fire alarm devices not associated with the above listed work. Components needing repair that are not described on the above quote will be susceptible to an additional cost.</p>			

Customer Note:		Subtotal	\$19,630.73
Sign for Approval:	Date:	Sales Tax (8.25%)	\$0.00
		Total	\$19,630.73