



3 Year Safety & Security Audit

July 21, 2026

Why?



TEC 37.108(b):

At least once every three years, each school district or public junior college district shall conduct a safety and security audit of the district's facilities. A district, or a person included in the registry established by the Texas School Safety Center under Section 37.2091 who is engaged by the district to conduct a safety and security audit, shall follow safety and security audit procedures developed by the Texas School Safety Center in coordination with the commissioner of education or commissioner of higher education, as applicable.

Audit Information



- Contracted with Tx Audit and EOP Services - Chris Gent
- Fully vetted through the Texas School Safety Center
- Extensive background and reference checks
- All campuses, Administration Building, MAC, Panther Stadium, Operations Building, MPower, ITC/DAEP

Audit Process



- Campus/Building staffs completed facility surveys prior to the audit; these surveys were specific to job title.
- Principals/Directors completed and Entrance Conference with Chris Gent prior to his inspection of the facility.
- The audit included an Intruder Detection Audit.
- Began on Monday, 3/16 and concluded on Thursday, 3/19

Auditor's Observations



- Chris was very complimentary of our Safety/Security protocols, processes, and overall culture of safety.
- “Your staff takes safety personal, it’s not just another thing they are required to do.”
- Zero exterior doors unlocked, propped, not functioning.
- Badge reader access points all operational.
- Complementary of our recent upgrades to surveillance cameras, camera monitoring software, and Catapult EMS
- Zero major concerns in our safety and security.

Area of Non-Compliance



TEC 38.008 - Each school in a school district with a grade level of seven or higher posts in a conspicuous location in the school gymnasium and each other place in a building where physical education classes are conducted (a notice regarding Anabolic Steroids)

➤ *Signage was not consistently displayed across MHS, MMS, and RVMS.*

Remedy: Brad Shelton and his athletic training staff have posted this notice in all required places and will replace any notices as necessary.

Completed June 8



Area of Non-Compliance

TEA School Safety Standard - Unless inside an exterior secured area, doors constructed of glass or containing glass shall be constructed or modified such that the glass cannot be easily broken and allow an intruder to open or otherwise enter through the door (for example, using forced entry-resistant film)

➤ *Shatter Proof film was missing from a vestibule door*

Remedy: Safe Haven Defense is our vendor for installing shatter proof film across the district. Upon inspection, we found 11 window or door panes requiring film.

Installation completed May 22

Safe Haven is located in Arizona. Ken Wolf has local vendors who could provide this service. Operations is adding a step to their window replacement process that includes shatter proof film installation.



Area of Non-Compliance

TEA School Safety Standard - All instructional facilities, including modular, portable buildings, must include the addition of graphically represented alphanumeric characters on both the interior and exterior of each exterior door location.

➤ *Door #8 missing an exterior number at Hewitt Elementary*

Remedy: Installation of #8 completed June 16

Work orders for exterior doors rise to the top of the work order que. Additionally, administrators contact Ken Wolf directly when exterior door issues arise to expedite the process.

Area of Non-Compliance



Fire Safety Code- Texas requires school districts to post highly specific, individualized evacuation maps near the exit doorway of every classroom. These diagrams must be placed at a height where students can easily see them and clearly outline two distinct ways to exit the building from that specific room.

- *The MAC did not have evacuation routes posted.*

Remedy: Maps delivered to Brad Shelton for installation June 8

Best Practice

- *Consistent Visitor entry signage installed at all district campuses.*



- Signs Delivered to Operations on June 2.
- Installation of signs on all campuses complete on June 16.



Best Practice

- *Remove any material that could prevent an exterior door from closing properly.*

Hewitt Elementary Playground Pea Gravel:

Operations asked a local company for a quote to remove the pea gravel. They will continue to contact the company for the quote. Ideally, the pea gravel is removed and an alternate material installed where required for soft landings.



Best Practice

- *Science Lab eyewash stations and emergency showers are tested and flushed regularly.*

MHS, MMS, RVMS Science Labs:

MISD Secondary Math and Science Coordinator Liza Qourzal and secondary science teachers are working to develop a reasonable schedule of maintenance for secondary science lab eyewash stations and emergency showers.



Best Practice



- *Mechanical, electrical and other equipment on ground level is surrounded by a protective enclosure.*



Hewitt Elementary Transformer:

Operations confirmed code requirements with OnCor and will construct a simple barrier to encourage students to walk around the transformer. The majority of campus moving is completed; operations will have time to devote to this project now.

Review and Next Steps



- Very positive & validating report from the auditor
- Non-compliance issues were largely related to signage
- Areas of non-compliance and best practices either have been addressed or a plan to address them is in place
- This information was shared with the District Safety & Security Committee on June 18, 2026
- Complete and submit the District Audit Survey to the Texas School Safety Center before September 15, 2026



Questions?