

MAINTENANCE REPORT
MAY 2026

Submitted by: Reid Reagan

Maintenance staff has been busy preparing for graduation. Clean-up and mowing of school grounds. Monitor and verify the fire/security alarms, reset as needed. In addition we have been ordering/stocking summer custodial supply orders.

BHS:

Setup for BHS track meet at stadium. Assist in set-up, clean-up and take down of decorations for Graduation activities. Auto shop roll-up door off track, cable jumped off drum, service restored. Install new gaskets to dishwasher, stop leaking.

BMS:

Install fire alarm pull station near the FACP, for fire drills. Assist in set-up, take down of the Staff Appreciation activities. Power outage damaged (1) boiler control screen.

BES:

Power outage, reset servers. 1 year bleacher maintenance inspection performed, minor adjustments made. Recharge kitchen cooler with refrigerant, service restored.

NAPI:

Dirty smoke detectors setting off fire alarms, replace faulty smoke detector and cleaned usable detectors, restored.

BULLSHOE VC/KWB:

Power outage caused power loss to server, system restored.

ANNEX:

Faulty GFI replaced, electricity restored.

BABB:

Power outage caused boilers to go into alarm/lockout status as precaution. Recharge kitchen cooler with refrigerant, service restored.