

FACILITIES/CONSTRUCTION REPORT

JUNE 2026

BHS HVAC:

6-3 Calm, warm@62 degrees. Heartland Mechanical drain refrigerant in system and replace (2) faulty solenoids on air handler unit #4, replace refrigerant, 1 worker.

6-4 Calm, warm@64 degrees. Heartland Mechanical pressurize system, monitor start-up of air handler unit #4, no leaks but operating on 1 circuit, 1 worker.

6-15 Calm, warm@70 degrees. Heartland Mechanical add refrigerant, pressurize system and check for leaks of air handler unit #4, on both (2) circuits, 2 workers.