

Henderson ISD Board Background

Subject: Consider the approval of a bus engine overhaul – estimated additional costs

Presented for: Action X

Report Only _____

Background Information

The Board previously approved an engine overhaul for unit B13 in March. During the repair process, additional issues were identified that were not visible during the initial inspection. The vendor has provided an estimated additional cost of \$3,000 to complete the necessary repairs.

Recommendation

It is recommended that the Henderson ISD Board of Trustees approve the additional estimated amount to finalize the repairs.

Contact Person(s)

Tom Hottman
Nikki Warner